



96-1173 Waihona St., Suite #B7
Pearl City, HI 96782
(808) 455-1522

Acct ID: Goodfellow Bros Proj No.: GBI024
Report Date: 09/01/2010
Project: Waimanalo Gulch Landfill - Nanakuli
Location: Drain Rock

Date Sampled: 08/27/2010
Sampled By: Dean Tabangcura
By Order Of: Ben
Order Number:

Client: Goodfellow Bros., Inc.

REPORT: Sieve Analysis

LAB NO: 21061-3
Test Method: See Below

Client PO: 13234

TEST RESULTS

Report No: 21061-3
Page 1 of 1

Description: Drain Rock

Sieve	% Passing	Low	High
3 in			
1 1/2 in	100		
1.00 in	66		
3/4 in	33		
1/2 in	11		
3/8 in	10		
No. 4	9		
No. 8			
No. 16			
No. 30			
No. 50			
No. 100			
No. 200	7.1		

using 1.25" screen

Test Method (As Applicable): ASTM C136 C117

Orig: Goodfellow Bros., Inc. (Waipahu, HI)
Attn: Ben H. (1-ec copy)
1-ec Goodfellow Bros., Inc. Attn: Doug R
1-cc Laboratory

Respectfully Submitted,
Construction Engineering Labs

Ronald A. Pickering II, President

THIS REPORT APPLIES ONLY TO THE STANDARDS OR PROCEDURES INDICATED AND TO THE SAMPLE(S) TESTED AND/OR OBSERVED AND ARE NOT NECESSARILY INDICATIVE OF THE QUALITIES OF APPARENTLY IDENTICAL OR SIMILAR PRODUCTS OR PROCEDURES, NOR DO THEY REPRESENT AN ONGOING QUALITY ASSURANCE PROGRAM UNLESS SO NOTED. THESE REPORTS ARE FOR THE EXCLUSIVE USE OF THE ADDRESSED CLIENT AND ARE NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION.

WMH001186